

EXHIBIT G


Failure mode, originally not grit blasted surface

Figure 13

zirconia
Bond
coat
alumina



Figure 14



Predominate interface of failure can vary

Figure 15

